



Quarterly Playground Inspection - 4 June 2019

Summary of Findings - 10 June 2019

On the 4 June 2019 Inspector Richard Randall from Dick Randall Services inspected all five play areas within the Worplesdon parish. This is a summary of findings from all five reports.

Fairlands Play Area

There is a deterioration in the rubber surface near the climbing boulder. (Low/Medium Risk - Monitor)

White House Lane, Jacobs Well Play Area

Multi-play unit. Bolt loose at base on right hand side of side steps causing slight movement. Remove caps and tighten. (Low/Medium Risk)

Small split in wet pour rubber on roundabout area. (Low Risk – Monitor)

Wood Street Green Play Seat Area

None.

Worplesdon Play Area

Worplesdon Teen Area

The MUGA unit has a piece missing from the corner leaving a bolt exposed and an edge. Recommended action is to consider repair. (Low Risk)

Shrinkage around the Typhoon wet pour is now at nearly 3 inches from the edge and is causing a trip hazard (High Risk – in need of urgent repair). There is also shrinkage around the blue centre graphic, (Medium Risk - Monitor) and around the edge of the yellow whizzer. (Low Risk – Monitor)

Worplesdon Toddler Area

Recent repairs to the wet pour rubber surfacing are starting to split apart on the double swing bay. (Low Risk)