



Quarterly Playground Inspection - 6 December 2019

Summary of Findings - 9 December 2019

On the 6 December 2019 Inspector Richard Randall from Dick Randall Services inspected all five play areas within the Worplesdon parish. This is a summary of findings from all five reports.

Fairlands Play Area

There is shrinkage of the wet pour rubber surface near the climbing boulder. **(Low Risk – Monitor)**

White House Lane, Jacobs Well Play Area

Small split in wet pour rubber on roundabout area. **(Low Risk – Monitor)**

Wood Street Green Play Seat Area

None.

Worplesdon Play Area

Worplesdon Teen Area

The edges of the wet pour underneath the basket swing bay are shrinking. **(Low Risk)**

Worplesdon Toddler Area

Repairs to the wet pour rubber surfacing are starting to split apart on the double swing bay. The repairs have now split back and there is now an edge to the raised rubber which could cause a trip hazard. The Inspector would suggest repairs before the split becomes wider and the trip higher. **(Medium Risk)**